
Extrusion Tips and Dies

Specifications



Item	Details
Tooling	Extrusion tips (guider tips) and dies
Methods	Pressure, semi-pressure and tubing tooling
Materials	Tool steel; tips with tungsten carbide or diamond (PCD or natural) inserts
Fit	To your crosshead make and model, drawing or used sample
Compounds	PVC, PE, PU, rubber and other insulation and jacket compounds
Supplied as	Tips, dies or matched sets

What to send for a quote

- Crosshead make and model
- Drawing of the tip and die, or a used set, with the part you need marked
- Pressure, semi-pressure or tubing tooling
- Conductor: solid, stranded or cabled, and its diameter
- Finished diameter over the insulation or jacket, and the compound
- On the drawing: bores, taper angles, land length, keyway, width and chamfers
- Quantity